

Date	Primary Road Class	Primary Road Name	Road Speed Limit	Second Road Class	Second Road Name	How Collision Occurred
09/03/2018	B5247	CARR HOUSE LANE	60	B5248	NORTH ROAD	V1 PULLS OUT OF B5248, TURNING NORTH ONTO B5247. V2 TRAVELLING S/B ON B5247. V2 UNABLE TO STOP, IMPACTING THE O/S OF V1.
28/08/2018	B5247	CARR HOUSE LANE	60	B5248	NORTH ROAD	DRIVER OF V1 HAS HAD A MEDICAL EPISODE AT THE WHEEL RELATING TO DIABETES. V1 HAS LOST CONTROL HIT A TREE AND OVERTURNED.
08/02/2018	UC	COCKER BAR ROAD	60	UC	COCKER BAR ROAD	V1 HAS BEEN TRAVELLING NORTH TO SOUTH ALONG NATIONAL SPEED LIMIT ROAD DURING HOURS OF DARKNESS. V1 HAS ENTERED SHARP RIGHT HAND S BEND AND HAS FAILED TO NEGOTIATE BEND LEAVING THE ROAD AND COMING TO REST IN A DITCH
28/01/2016	B5248	COCKER BAR ROAD	60	UC	UNNAMED FARM TRACK	V001 TRAVELLING ON SINGLE CARRIAGEWAY ROAD, GOVERNED BY NATIONAL SPEED LIMIT, LOSES CONTROL ON SHARP RIGHT HAND BEND AND LEAVES ROAD. V001 ENTERS DITCH FRONT FIRST.
24/03/2018	UC	EYES LANE	30	UC	BACK LANE	VEHICLE 1 HAS BEEN TRAVELLING SOUTH ALONG EYES LANE BEING FOLLOWED BY VEHICLE 2. VEHICLE 1 HAS PANICKED THINKING VEHICLE 2 IS TOO CLOSE AND CRASHED INTO A HEDGEROW
31/08/2018	UC	FLAG LANE	30	UC	BAKC LANE	VEHICLE 1 HAD BEEN TRAVELLING DOWN ROAD 1. VEHICLE 1 IS BELIEVED TO HAVE BEEN TRAVELLING AT AN EXCESSIVE SPEED. VEHICLE 1 HAS APPROACHED A BEND IN THE ROAD WHICH BENT TO THE RIGHT. IN ADDITION TO THIS, THE JUNCTION TO ROAD 2 WAS DIRECTLY IN FRONT TO THE LEFT. VEHICLE 1 HAS APPROACHED THE BEND AND HAS DRIVEN STRAIGHT ONTO THE PAVEMENT, STRAIGHT THROUGH A HEDGE PERIMETER AND HAS COLLIDED WITH A TREE. IT IS BELIEVED THAT VEHICLE 1 HAD NOT BRAKED DURING THIS DUE TO THERE BEING NO SKID MARKS ON THE ROAD SURFACE. IT IS BELIEVED THAT BOTH CASUALTIES 1 AND 2 WERE NOT WEARING SEAT BELTS DUE TO THEM NOT HAVING THEM ON AT THE TIME OF POLICE ARRIVAL. IN ADDITION TO THIS, THERE WERE TWO ROUND SHAPED CRACKS IN THE WINDSCREEN WHICH INDICATED THAT BOTH CASUALTIES HAD HEADBUTTED IT.
11/03/2017	B5247	FLAG LANE	60	UC	SOUTH ROAD	VEHICLE 1 WHICH IS DESCRIBED AS A WHITE FLAT BED TRUCK PASSED TOO CLOSE TO A PEDAL CYCLIST HITTING HIM AS HE PASSED, THIS HAS CAUSED THE PEDAL CYCLIST TO GO OVER THE HANDLE BARS OF HIS BIKE BEFORE LANDING ON THE FLOOR HITTING HIS HEAD AS HE LANDED
27/02/2017	A59	LIVERPOOL ROAD	40	B5247	CARR HOUSE LANE	CAR EMERGES FROM LAY-BY INTO PATH OF PASSING CAR SPINNING THIS CAR INTO SIDE OF LORRY FURTHER DOWN LAY BY.
04/02/2016	A59	LIVERPOOL ROAD	60	UC	CARR HOUSE LANE	VEHICLE 1 MOTOR CAR APPROACHES, REAR OF VEHICLE 2 MOTORCAR THAT WAS OVERTAKING STATIONARY VEHICLE 3 PSV AND DUE TO WET ROAD, FAILS TO SEE STATIONARY VEHICLES AND COLLIDES WITH REAR OF VEHICLE 2 CAUSING 4 VEHICLE SHUNT,
15/01/2016	A59	LIVERPOOL ROAD	40	B5247	CARR HOUSE LANE	DRIVER OF VEHICLE ONE HAS FAILED TO NOTICE VEHICLE TWO AHEAD SLOWING AND HAS COLLIDED WITH THE REAR OF IT, PUSHING IT INTO THE REAR OF VEHICLE THREE
25/08/2017	A59	LIVERPOOL ROAD	40	UC	CARR HOUSE LANE	VEH 1 DOES NOT SEE STANDING SLOWING TRAFFIC AHEAD AND COLLIDES WITH REAR OF VEH 2 WHO COLLIDES WITH REAR OF VEH 3 WHO COLLIDES WITH REAR OF VEH 4 CONSETINA EFFECT
17/11/2016	B5248	NORTH ROAD	50	B5427	CARR HOUSE LANE	V1 TRAVELS ALONG NORTH ROAD, BRETHERTON TOWARDS THE JUNCTION WITH CARR HOUSE LANE. A SMALL LINE OF STSTIONARY TRAFFIC IS WAITING AT THE JUNCTION AHEAD OF V1. AS V1 ROUNDS SLIGHT LEFT HAND BEND IT TAKES EVASIVE MANOEUVRE TO THE OFF SIDE TO AVOID COLLISION WITH STATIONARY VEHICLE AHEAD. V1 MOVES INTO OFFSIDE LANE AND COLLIDES WITH V2 WHICH HAS JUST ENTERED NORTH ROAD FROM CARR HOUSE LANE. BOTH VEHICLES ARE DAMAGED TO THE FRONT NEARSIDE.
28/05/2016	UC	NORTH ROAD	60	UC	DOLES LANE	DRIVER TRAVELLING ALONG NATIONAL SPEED LIMIT ROAD, FOR UNKNOWN REASON HAS LOST CONTROL BRIEFLY LEAVING THE CARRIAGEWAY FOR UNKNOWN REASON, THE REAR OF THE VEHICLE HAS LOST CONTROL, THE DRIVER HAS TRIED TO CORRECT THIS BY STEERING BUT THE
25/03/2017	B5248	NORTH ROAD	50	UC	POMPIAN BROW	VEHICLE HAS LOST CONTROL AND ROLLED INTO A DITCH
14/04/2016	UC	NORTH ROAD	60	UC	POMPIAN BROW	VEHICLE 1 (AN EMERGENCY VEHICLE) HAS BEEN TRAVELLING TO AN INCIDENT. WHILST NEGOTIATING SHARP RIGHT HAND BENDS HAS MISJUDGED THE ROAD. VEHICLE 1 HAS LEFT THE ROAD AND COME TO REST ON ITS NEAR SIDE IN A DITCH.
06/06/2018	B5247	SOUTH ROAD	30	UC	POMPIAN BROW	CYCLIST HAS BEEN TRAVELLING IN THE DIRECTION OF CARR HOUSE LANE AT THE JUNCTION OF EYES LANE. (VEHICLE 1) HAS BEEN FOLLOWING BEHIND THE BIKE AND ATTEMPTED TO OVERTAKE ON THE BEND AS A VAN WAS APPROACHING IN THE OPPOSITE DIRECTION. DRIVER'S NEARSIDE WING HAS COLLIDED WITH THE HANDLEBARS OF THE BIKE CAUSING THE CYCLIST TO COME OFF HIS BIKE. THE DRIVER STOPPED AND CHECKED ON THE CYCLIST. THE CYCLIST LATER ATTENDED RPH WERE HE WAS DIAGNOSED WITH A MILD CONCUSSION, PULLED NECK MUSCLES, GASH TO LEFT KNEE, CUT TO RIGHT HAND AND FRACTURE TO LEFT HAND. CYCLIST WAS NOT WEARING ANY PROTECTIVE EQUIPMENT AT THE TIME.